

EXPERIMENT 1


Aim: Study and Practice of Orthogonal & Oblique Cutting on a Lathe.


Apparatus: Lathe Machine

Theory:

It appears from the diagram in the following figure that while turning ductile material by a sharp tool, the continuous chip would flow over the tool's rake surface and in the direction apparently perpendicular to the principal cutting edge, i.e., along orthogonal plane which is normal to the cutting plane containing the principal cutting edge. But practically, the chip may not flow along the orthogonal plane for several factors like presence of inclination angle λ , etc. The role of inclination angle λ on the direction of chip flow is schematically shown in figure which visualizes that,

- when $\lambda=0$, the chip flows along orthogonal plane, i.e., $\rho = 0$
- when $\lambda \neq 0$, the chip flow is deviated from π and $\rho = \lambda$ where ρ is chip flow deviation (from π) angle





Orthogonal cutting: when chip flows along orthogonal plane, π , i.e., $\rho = 0$

In Orthogonal cutting

- 1- Cutting tool travel in the direction perpendicular to the cutting edge.
- 2- The cutting edge clear either end of work piece.
- 3- Chip flows in the direction perpendicular to the cutting edge.
- 4- Two mutually perpendicular cutting forces act on the work piece.

Oblique cutting: when chip flow deviates from orthogonal plane, i.e. $\rho \neq 0$ But practically ρ may be zero even if $\lambda = 0$ and ρ may not be exactly equal to λ even if $\lambda \neq 0$. Because there are some other (than λ) factors also which may cause chip flow deviation.

In Oblique cutting

- 1- Cutting edge travels, making an angle with the normal of cutting edge.
- 2- The cutting edge may or may not clear either end of work piece.
- 3- Chip flows, making an angle with normal of cutting edge.
- 4- Three mutually perpendicular forces are involved.

Result: Hence the study of Orthogonal & Oblique Cutting on a Lathe is completed.

EXPERIMENT 2

Aim: Machining time calculation and comparison with actual machining time while cylindrical turning on a Lathe and finding out cutting efficiency.

Apparatus: Lathe Machine

Theory:

The major aim and objectives in machining industries generally are;

- reduction of total manufacturing time, T
- increase in MRR, i.e., productivity
- reduction in machining cost without sacrificing product quality
- increase in profit or profit rate, i.e., profitability.

Hence, it becomes extremely necessary to determine the actual machining time TC required to produce a job mainly for,

- assessment of productivity
- evaluation of machining cost
- measurement of labour cost component assessment of relative performance or capability of any machine tool, cutting tool, cutting fluid or any special or new techniques in terms of saving in machining time.

The machining time, TC required for a particular operation can be determined roughly by calculation i.e., estimation or precisely, if required, by measurement. Measurement definitely gives more accurate result and in detail but is tedious and expensive. Whereas, estimation by simple calculations though may not be that accurate, is simple, quick and inexpensive. Hence, determination of machining time, specially by simple calculations using suitable equations is essentially done regularly for various purposes.

Procedure:

The factors that govern machining time will be understood from a simple case of machining.

A steel rod has to be reduced in diameter from D_1 to D_2 over a length L by straight turning in a centre lathe as indicated in Fig.




Fig. Estimation of machining time in turning.

Here,
$$T_C = \frac{L_C}{N s_o} \times n_p$$

where, L_C = actual length of cut
 $= L + A + O$

A, O = approach and over run as shown

N = spindle speed, rpm

s_o = feed (tool), mm/rev

n_p = number of passes required

Speed, N, is determined from cutting velocity, V_C

$$V_C = \frac{\pi D N}{1000} \text{ m/min}$$

where, D = diameter of the job before cut

Therefore,
$$N = \frac{1000 V_C}{\pi D}$$

The number of passes, n_p is mathematically determined from,

$$n_p = \frac{D_1 - D_2}{2t}$$

where, t = depth of cut in one pass, mm.

Calculations:-

S.N.	L	A	O	Lc	Vc	D	N	So	D1	D2	T	n _p	Tc

Where,

L= length of the work piece in mm;

A= approach run in mm;

O= over run in mm;

Lc=actual length of cut in mm;

Vc= cutting velocity in mm/min;

D= diameter of the job before cut in mm;

N=spindle speed in rpm;

So= tool feed in mm/rev;

D1= initial diameter before passes in mm;

D2=final diameter after passes in mm;

t=depth of cut in one pass in mm;

n_p =no of passes;

Tc=machining time in min;

Result: The machining time of the turning operation is done and compared.

EXPERIMENT 3

Aim: To study the Tool Life while Milling a component on the Milling Machine.

Apparatus: Milling Machine

Theory:

Tool life: Time of cutting during two successive milling or indexing of the tool. Tool life is the length of cutting time that a tool can be used or a certain flank wear value has occurred (0.02”).

Tool life criteria in production

1. Complete failure of the cutting edge;
2. Chips becomes ribbony, stingy, and difficult to dispose of;
3. Degradation of the surface finish on the work;
4. Cumulative cutting time or workpiece count.

Taylor’s tool life equation:

$$VT^n = C$$

V = cutting speed

n = cutting exponent

C = cutting constant

T = tool life

n and C depend on speed, work material, tool material, etc.

Cutting Speed can be obtained by the formula as shown:

$$N = (V * 1000) / (\pi * d)$$

Where :

N=spindle speed in rpm;

V=cutting speed in m/min;

d=diameter of cutter in mm;

Procedure:

1. Determine the cutting speed by using given d and N values.
2. Apply Taylor’s equation and the n and C values, we can solve for tool life.

Calculations:-

S.N.	n	C	d	N	V	T

Result: Thus the tool life of milling cutter is found out.


EXPERIMENT 4

Aim: To study Tool wear of a cutting tool while Drilling on a Drilling Machine.

Apparatus: Drilling Machine


Theory:

Tool wears are classified as shown below



Three basic wear mechanisms involved in tool wear:

1. Adhesive wear



3. Diffusion wear




Figure 2. Flank and crater wear on the faces of cutting tool.

Crater wear:

Consists of a concave section on the tool face formed by the action of the chip sliding on the surface. Crater wear affects the mechanics of the process increasing the actual rake angle of the cutting tool and consequently, making cutting easier. At the same time, the crater wear weakens the tool wedge and increases the possibility for tool breakage. In general, crater wear is of a relatively small concern.

Flank wear:

Occurs on the tool flank as a result of friction between the machined surface of the work piece and the tool flank. Flank wear appears in the form of so-called wear land and is measured by the width of this wear land, VB, Flank wear affects to the great extend the mechanics of cutting. Cutting forces increase significantly with flank wear. If the amount of flank wear exceeds some critical value ($VB > 0.5\sim 0.6$ mm), the excessive cutting force may cause tool failure.

Catastrophic wear (Built up Edge):

In single point cutting of metals, a **built up edge** (BUE) is an accumulation of material against the rake face that seizes to the tool tip, separating it from the chip. The built up edge effectively changes tool geometry and rake steepness. It also reduces the contact area between the chip and the cutting tool, leading to:

- A reduction in the power demand of the cutting operation.
- Slight increase in tool life, since the cutting is partly being done by the built up edge rather than the tool itself.

Abrasion wear: this is a mechanical wearing action due to hard particles in the work material gouging and removing small portions of the tool.

Location: both on rake and flank faces.

Adhesion wear: as the cutting chip flows across the tool under high temperature and high pressure, small particles of the tool are "welded" to the chip surface and taken away.

Location: mostly on the rake face.

Diffusion wear: is a process in which an exchange of atoms takes place across a close contact at the tool-chip boundary between two materials.

Location: on the rake face.

EXPERIMENT 5

Aim: To study the Speed, Feed, Tool, Preparatory (Geometric) and miscellaneous functions for NC part programming

Apparatus: NC Milling Machine

Theory:

Part program: A computer program to specify

- Which tool should be loaded on the machine spindle?
- What are the cutting conditions (speed, feed, coolant ON/OFF etc.)
- The start point and end point of a motion segment
- How to move the tool with respect to the machine.

CNC G-codes: Preparatory Functions– involve actual tool moves.

- G00 - Positioning at rapid speed; Mill and Lathe
- G01 - Linear interpolation (machining a straight line); Mill and Lathe
- G02 - Circular interpolation clockwise (machining arcs); Mill and Lathe
- G03 - Circular interpolation, counter clockwise; Mill and Lathe
- G04 - Mill and Lathe, Dwell
- G09 - Mill and Lathe, Exact stop
- G10 - Setting offsets in the program; Mill and Lathe
- G12 - Circular pocket milling, clockwise; Mill
- G13 - Circular pocket milling, counterclockwise; Mill
- G17 - X-Y plane for arc machining; Mill and Lathe with live tooling
- G18 - Z-X plane for arc machining; Mill and Lathe with live tooling
- G19 - Z-Y plane for arc machining; Mill and Lathe with live tooling
- G20 - Inch units; Mill and Lathe
- G21 - Metric units; Mill and Lathe
- G27 - Reference return check; Mill and Lathe
- G28 - Automatic return through reference point; Mill and Lathe
- G29 - Move to location through reference point; Mill and Lathe (slightly different for each machine)
- G31 - Skip function; Mill and Lathe
- G32 - Thread cutting; Lathe
- G33 - Thread cutting; Mill
- G40 - Cancel diameter offset; Mill. Cancel tool nose offset; Lathe
- G41 - Cutter compensation left; Mill. Tool nose radius compensation left; Lathe
- G42 - Cutter compensation right; Mill. Tool nose radius compensation right; Lathe
- G43 - Tool length compensation; Mill
- G44 - Tool length compensation cancel; Mill (sometimes G49)
- G50 - Set coordinate system and maximum RPM; Lathe
- G52 - Local coordinate system setting; Mill and Lathe
- G53 - Machine coordinate system setting; Mill and Lathe
- G54~G59 - Work piece coordinate system settings #1 to #6; Mill and Lathe

G61 - Exact stop check; Mill and Lathe
G65 - Custom macro call; Mill and Lathe
G70 - Finish cycle; Lathe
G71 - Rough turning cycle; Lathe
G72 - Rough facing cycle; Lathe
G73 - Irregular rough turning cycle; Lathe
G73 - Chip break drilling cycle; Mill
G74 - Left hand tapping; Mill
G74 - Face grooving or chip break drilling; Lathe
G75 - OD groove pecking; Lathe
G76 - Fine boring cycle; Mill
G76 - Threading cycle; Lathe
G80 - Cancel cycles; Mill and Lathe
G81 - Drill cycle; Mill and Lathe
G82 - Drill cycle with dwell; Mill
G83 - Peck drilling cycle; Mill
G84 - Tapping cycle; Mill and Lathe
G85 - Bore in, bore out; Mill and Lathe
G86 - Bore in, rapid out; Mill and Lathe
G87 - Back boring cycle; Mill
G90 - Absolute programming
G91 - Incremental programming
G92 - Reposition origin point; Mill
G92 - Thread cutting cycle; Lathe
G94 - Per minute feed; Mill
G95 - Per revolution feed; Mill
G96 - Constant surface speed control; Lathe
G97 - Constant surface speed cancel
G98 - Per minute feed; Lathe
G99 - Per revolution feed; Lathe

CNC M Codes: Miscellaneous Functions – involve actions necessary for machining (i.e. spindle on/off, coolant on/off).

M00 - Program stop; Mill and Lathe
M01 - Optional program stop; Lathe and Mill
M02 - Program end; Lathe and Mill
M03 - Spindle on clockwise; Lathe and Mill
M04 - Spindle on counterclockwise; Lathe and Mill
M05 - Spindle off; Lathe and Mill
M06 - Tool change; Mill
M08 - Coolant on; Lathe and Mill
M09 - Coolant off; Lathe and Mill
M10 - Chuck or rotary table clamp; Lathe and Mill
M11 - Chuck or rotary table clamp off; Lathe and Mill
M19 - Orient spindle; Lathe and Mill

M30 - Program end, return to start; Lathe and Mill
M97 - Local sub-routine call; Lathe and Mill
M98 - Sub-program call; Lathe and Mill
M99 - End of sub program; Lathe and Mill

CNC N Codes: Gives an identifying number for each block of information.

X, Y, and Z codes are used to specify the coordinate axis.

- Number following the code defines the coordinate at the end of the move relative to an incremental or absolute reference point.
- The number may require that a specific format be used (i.e. 3.4 means three numbers before the decimal and four numbers after the decimal).

I, J, and K codes are used to specify the coordinate axis when defining the center of a circle.

- Number following the code defines the respective coordinate for the center of the circle.
- The number may require that a specific format be used (i.e. 3.4 means three numbers before the decimal and four numbers after the decimal).

F-code: used to specify the feed rate

S-code: used to specify the spindle speed

T-code: used to specify the tool identification number associated with the tool to be used in subsequent operations.

R-code:

- Retract distance when used with G81, 82, and 83.
- Radius when used with G02 and G03.


P-code: Used to specify the dwell time associated with G04.

EXPERIMENT 6

Aim: To study the part programming on a NC Milling Machine for a Rectangular Slot.

Apparatus: NC Milling Machine

Procedure:



N01 G90 EOB

N02 G17 EOB

N03 M06 EOB

N04 M04 S1200

N05 G01 X27.5 Y-7.5 F30 EOB

N06 G01 Z-5.6 EOB

N07 L601 EOB

N08 Z-6.3 EOB

N09 L601 EOB N140 M17 EOB

N010 Z-7.0 EOB

N011 L601 EOB

N012 Z5 EOB

N013 GO X0 Y0 EOB

N014 M05 EOB

N015 M30 EOB

EXPERIMENT 7

AIM: To study the Part Programming and Proving on a NC Milling Machine:-

- a. Point to Point Programming
- b. Absolute Programming
- c. Incremental Programming

Apparatus: NC Milling Machine

Procedure:

Point to Point Programming

In point to point system, the machining is done at specific positions. The working-piece remains unaffected as the tool moves from one position to the next. The system is the simplest. In fig.1, after drilling the hole at position A, the tool moves to position B, along the dotted line. A drilling machine is the best example of point to point system.





Figure-1

CNC Absolute Programming G90 Example Code

With absolute positioning, we tell the machine where to move based on a common point, called X0 Y0 and Z0. Every time we need to move to a certain position, the ending point of that move is in direct relationship to this “common point”.

This CNC example code illustrates the usage of CNC Absolute Programming G90 G-Code and Incremental Programming G91 G-Code, as well as the usage of Circular Interpolation G-Code (G02/G03).



CNC Mill Programming Absolute Incremental G90 G91 Example Code

Mill Circular Interpolation G02 G03 with R

```
G92 X200 Y40 Z0
G90 G03 X140 Y100 R60 F300
G02 X120 Y60 R50
```

Mill Circular Interpolation G02 G03 with I

```
G92 X200 Y40 Z0
G90 G03 X140 Y100 I-60 F300
G02 X120 Y60 I-50
```

CNC Incremental Programming G91 Example Code

With incremental positioning, we are telling the machine where to go in relationship to where it currently is at. Basically like a set of directions given from where the machine stopped last.

Mill Circular Interpolation G02 G03 with R

```
G91 G03 X-60 Y60 R60 F300
G02 X-20 Y-40 R50
```

Mill Circular Interpolation G02 G03 with I

```
G91 G03 X-60 Y60 I-60 F300
G02 X-20 Y-40 I-50
```

EXPERIMENT 8

AIM: To study the construction and operation of a shaping machine.


REQUIREMENTS:


1. Shaping Machine.

PARTS:

Important parts of the machine are:

1. Frame (Machine Column)
2. Ram
3. Machine Table with table support
4. Saddle
5. Ram Head with Tool Slide and Tool Post with Clapper Box Block
6. Main Gearing (Gear Train and oscillating slider crank mechanism)
7. Drive (Electro Motor)





INTRODUCTION:

The shaper is a machine tool used primarily for:

1. Producing a flat or plane surface which may be in a horizontal, a vertical or an angular plane.
2. Making slots, grooves and keyways
3. Producing contour of concave/convex or a combination of these

WORKING PRINCIPLE:

The job is rigidly fixed on the machine table. The single point cutting tool held properly in the tool post is mounted on a reciprocating ram. The reciprocating motion of the ram is obtained by a quick return motion mechanism. As the ram reciprocates, the tool cuts the material during its forward stroke. During return, there is no cutting action and this stroke is called the idle stroke. The forward and return strokes constitute one operating cycle of the shaper.


CONSTRUCTION:

The main parts of the Shaper machine are Base, Body (Pillar, Frame, Column), Cross rail, Ram and tool head (Tool Post, Tool Slide, Clamper Box Block).

Base: The base is a heavy cast iron casting which is fixed to the shop floor. It supports the body frame and the entire load of the machine. The base absorbs and withstands vibrations and other forces which are likely to be induced during the shaping operations.

Body (Pillar, Frame, Column): It is mounted on the base and houses the drive mechanism compressing the main drives, the gear box and the quick return mechanism for the ram movement. The top of the body provides guide ways for the ram and its front provides the guide ways for the cross rail.

PRINCIPLE OF PRODUCING FLAT SURFACE IN SHAPING MACHINE:



Cross rail: The cross rail is mounted on the front of the body frame and can be moved up and down. The vertical movement of the cross rail permits jobs of different heights to be accommodated below the tool. Sliding along the cross rail is a saddle which carries the work table.

Ram and tool head: The ram is driven back and forth in its slides by the slotted link mechanism. The back and forth movement of ram is called stroke and it can be adjusted according to the length of the work piece to be-machined.

OPERATIONS:

Shaping is a technique with straight-lined motion (cutting and feed motion).

The feed motion takes place in steps.

The work piece clamping fixture (compound slide) consists of saddle and machine table.

The machine table is additionally supported.

The ram carries the ram head consisting of swivel-head plate, tool slide, clapper box with tool block and tool holder (tool post).

During the working stroke the tool block rests on the clapper box (as a result of the cutting pressure), during the return stroke it is lifted. In this way the tool tip is protected. With older shaping machines the tool is dragging over the work-piece during the return stroke. The working position is reached by the dead weight and, thus, by falling back.

Modern machines have an automatic tool lifter. For shaping oblique surfaces the tool slide can be swiveled on the swivel-head plate. In order to maintain the mobility of the tool block, it is also possible to set the clapper box on the tool slide at an angle, i.e. to swivel it in the circular slot.